

Damage as of 16 Aug. from 15 Aug. 2008 Rains



Left – Dining room ceiling fixture: water overflowed onto wood floor and then into basement.

Below – Residue water collected from leaks in dining room ceiling.



Left – Living room: water seepage at seams between sheetrock in ceiling.