

Damage as of 18 Aug. from 15 Aug. 2008 Rains



Left – Bathroom ceiling collapse from weight of rain-soaked insulation and sheetrock.

Below – Broken shower ceiling tiles after sheetrock collapse.

